

Statement of Deficiencies

5331-E: Vehicle in Good Repair

Not Met

5331.E. The vehicle shall be maintained in good repair.

Finding:

7331.E. (OLD TAG# 5331.E.) The Provider's vehicle was not maintained in good repair.

FINDINGS INCLUDE:

Specialist observed the tire wear indicator to be showing on the front passenger side tire of the center bus. The outside treads of the tire show more wear than the inside treads of the tire, which may signify a possible mechanical issue with the front end of the bus.
