Date - 05/13/2019 License # - 51439 Action Code - 521 - ONSITE FULL INSP & MEASUREMENT

## Statement of Deficiencies

## 2101.A.8.: Vehicle in Good Repair

**Not Met** 

2101.A.8.: Vehicles shall be maintained in good repair.

## Finding:

2101.A.8. Based on observations on 05/13/2019, the center vehicle was not maintained in good repair as evidenced by the van's back passenger door located on the right side of the vehicle failed to open from the outside as specialist attempted to open the door. Per S3's statement, the latch needs to be replaced and he will correct as soon as possible. This was not corrected prior to specialist departure.