Date - 03/13/2014 License # - 1646 Acton Code - 5

## Statement of Deficiencies

7305-E: State Fire Marshal Not Met

7305-E: The provider shall have documentation of yearly safety inspection and current approval from the Office of State Fire Marshal.

## Finding:

7305-E Based on record review: The Provider lacked documentation of a current annual fire safety inspection and approval from the Office of State Fire Marshal. The specialist observed the fire marshal completed an annual inspection on 2/20/2014 and the center was not acceptable for license due to the fire alarm not working. A fire watch log shall be implemented hourly and continued by the center until the alarms have been verified as operational by the Shreveport district office.