

Statement of Deficiencies

1903.E.6.: Outdoor - Crawlspace

Not Met

1903.E.6.: Crawlspace and mechanical, electrical, or other hazardous equipment shall be made inaccessible to children.

Finding:

1903.E.6. Based on observations: Electrical or other hazardous equipment is not inaccessible to children as Specialist observed two air conditioning units in the outdoor play area to the left side of the center building to be accessible to children. The cyclone/chain link fencing surrounding the A/C units have two fence posts which have rusted and collapsed, not allowing for secure fencing to prevent children from coming into contact with the A/C units. The fencing is lying upon the air conditioning units. The air conditioning units pose a electrical shock hazard. S1 stated three fencing contractors have come by to give repair estimates, but the fencing has not been repaired to date.
