

## ***Statement of Deficiencies***

### **1903-E.6: Outdoor - Crawlspace**

**Not Met**

1903-E.6: Crawlspace and mechanical, electrical, or other hazardous equipment shall be made inaccessible to children.

#### **Finding:**

1903-E.6 Based on observations: Crawlspace are not inaccessible to children as Specialist observed a shed placed on blocks within the outdoor play area of the Head Start to lack full protective skirting to prevent children from crawling under and becoming entrapped. Specialist observed a storage shed in the playground for the regular Head Start with wooden lattice covering the crawlspace under the shed to have become rotten and in disrepair. Specialist observed the shed to have a 1 1/2 foot section missing along the left side of the shed building and a 1 foot section missing at the rear of the shed building. S24 stated the wooden lattice skirting surrounding the shed may have become damaged during a recent treatment for termites.

---