Date - 08/04/2011 License # - 8591 Acton Code - 5

Statement of Deficiencies

5325-G: Equipment in Good Repair

Not Met

5325.G. All play equipment and equipment necessary for the operation of the center shall be maintained in good repair.

Finding:

7325.G (old tag 5325.G.) The provider did not maintain equipment necessary for the operation of the center in good repair as evidence by: specialist observation in building 2: the flooring in the area closest to the doorway is ripped at the seam and is detached from the main floor. Paint sections are detached and peeling from the wall next to the doorway.