

## ***Statement of Deficiencies***

### **2101.A.8.: Vehicle in Good Repair**

**Not Met**

2101.A.8.: Vehicles shall be maintained in good repair.

#### **Finding:**

2101.A.8. Based on observations, the vehicle failed to be in good repair as evidenced by the 1988 International yellow bus had 8 seats with holes and the 1993 International yellow bus had 6 seats with holes and 2 seats with holes that exposed the stuffing. S1 stated that the seats were repaired on the 1993 International yellow bus after the visit on 07/30/2019 and was not aware of the damage. This was not corrected prior to specialist departure.

---