Date - 10/31/2019 License # - 1308 Action Code - 6 - FOLLOW-UP to ANNUAL SURVEY

Statement of Deficiencies

1903.E.6.: Outdoor - Crawlspaces

Not Met

1903.E.6.: Crawlspaces and mechanical, electrical, or other hazardous equipment shall be made inaccessible to children.

Finding:

1903.E.6. Based on observations on 10/31/19 at 11:50am crawl space beneath building in play yard failed to be completely enclosed as part of the building skirt is missing and another part of it is loose from the building on the other side of play yard. Note: S1 reports that this is on the repair list but maintenance man is out for surgery.