Date - 02/19/2015 License # - 13568 Acton Code - 25

Not Met

Statement of Deficiencies

7323-B.1: Outdoor - Direct Exit

7323-B.1: Outdoor play space with a direct exit from the center into the outdoor play yard shall be available. If the exit does not open directly onto the play yard, the outdoor play yard shall be attached to the facility in such a manner to ensure that the children are continuously protected by a fence while going to and/or from the outdoor play yard.

Finding:

7323-B.1 Based on observations: The outdoor play space lacked a direct exit from the center into the outdoor play yard. Note: The play yard is currently not being used as it is under construction.