Date - 03/21/2019 License # - 13826 Action Code - 6 - FOLLOW-UP to ANNUAL SURVEY

Statement of Deficiencies

1903.E.6.: Outdoor - Crawlspaces

Not Met

1903.E.6.: Crawlspaces and mechanical, electrical, or other hazardous equipment shall be made inaccessible to children.

Finding:

1903.E.6. Based on observations: Electrical or other hazardous equipment is not inaccessible to children as Specialist observed two air conditioning units in the outdoor play area to the left side of the center building to be accessible to children. The cyclone/chain link fencing surrounding the A/C units have two fence posts which have rusted and collapsed, not allowing for secure fencing to prevent children from coming into contact with the A/C units. S3 stated the fencing will be repaired within the next two weeks.