Date - 05/29/2012 License # - 15232 Acton Code - 16

Statement of Deficiencies

7325-G: Equipment in Good Repair

Not Met

7325-G: All play equipment and equipment necessary for the operation of the center shall be maintained in good repair.

Finding:

*****NEW7325-G Based on observations: The provider did not maintain play equipment and equipment necessary for the operation of the center in good repair as ~evidenced by specialist observed 3 of 4 Flouresent lights not working in the T-Building which houses the 2-3 yr old children, specialist also observe 3 floor tiles that are missing and needs to be replaced in this same room.