

Statement of Deficiencies

2101.A.8.: Vehicle in Good Repair

Not Met

2101.A.8.: Vehicles shall be maintained in good repair.

Finding:

2101.A.8. Based on observations at 9:48 AM, the center vehicle failed to be maintained in good repair as evidenced by specialist observed the center's White Ford van did not have a rear view mirror secured on the inside of the front windshield. Specialist observed the rear view mirror inside the van in the front console. Per S2's statement, S1 attempted to secure the mirror before but it fell off again. Specialist allowed S1 to correct the rear view mirror on 07/29/2019. This was not corrected prior to specialist departure.
